Certificate of Crash Test according to

ISO 10542-1:2012 Wheelchair tiedown and occupant-restraint systems - SWM
&
ISO 7176-19 – 2022 Wheeled mobility devices for use as seats in motor vehicles

This report serves solely as documentation for the test results. The tested objects have been selected by the client without the assistance of Dahl Engineering.

Assignment:	Crash testing of wheelchair and WTORS according to ISO 7176-19 sections 5.2, 5.2.1 and 5.2.2. as well as ISO 10542 sections 5.2.4 and 5.2.5
Date of testing:	23 May 2022
Test object/Wheelchair:	Medema MC 1144 Spinalus 3 with an adaptation kit for Dahl docking systems, utilising Dahl kit #503236
Mass of wheelchair:	174,5 kg.
Serial no:	not informed
WTORS:	Dahl WTORS that meet requirements set out in ISO 10542 Wheelchair restraint system – Dahl Docking Station Occupant restraint – Dahl 3p. shoulder and lap belt #500984, all items certified by TÜV Rheinland test report no. 175XS0156
Test dummy/ATD:	The test was carried out using a Hybrid II 50% Male dummy with a mass of 77 kg.
Measuring:	The deceleration was measured by accelerometers mounted on the crash test sled.
Photography:	The test was filmed with a high speed camera at 500 fps. Still pictures, pre and post test, was also taken.
Test results:	See page 2
Sled deceleration and speed:	See page with plotted graph and speed

Section	Details	X if correct
5.2.1	**During the test**	
	Horisontal excursion limits	
	Wheelchair point P ≤ 200 mm [Xwc]	54
	ATD knee ≤ 375 mm[Xknee]	199
	ATD front of head ≤ 650 mm [XheadF]	464
	ATD rear of head ≤ 450 [XheadR]	-280
	The knee excursion exceeded the wheelchair P point excursion	X
	(Batteries on powered wheelchairs) did not move completely outside the wheel-chair footprint or move into the wheelchair user´s space or contact with ADT legs	X
5.2.2	**After the test**	
	The wheelchair remained in an upright position on the platform	X
	The ADT remained in the wheelchair with its torso at an angle of not more than 45º to the vertical, when viewed from any direction	X
	There were no visible signs of material failure on the wheelchair securing points	X
	There were no components, fragments or accessories of the wheelchair with a mass of more than 100g that completely separated from the wheelchair	X
	There were no fragmented or separated component, that may contact the occupant, produced with sharp edges less than radius 2 mm	X
	There were no visible signs of failure on the wheelchairs primary load carrying components	X
	There were no visible signs of failure on the wheelchairs seat adjusters	X
	The ADT was removed from the wheelchair without the use of tools	X
	The wheelchair was released from the tie-down system without the use of tools	X
	The post test decrease of the mean H-point height is not more than 20%	X

The presented samples meet the requirements set out in the above mentioned standard.

Test Laboratory: Dahl Engineering - Research and Testing Laboratory
Løvevej 3 - DK-7700 Thisted - Denmark
Phone: 45 96180077 - Fax: 45 96180078
e-mail: Dahl@dahlengineering.dk – web page: www.dahlengineering.dk

Thisted 17. June 2022

Claus Dahl Pedersen
Head of test laboratory



25/04-2025 rev. I:
Correction of ISO Standard reference version in document header (from: 2008, to: 2022)

Plotted graph and speed


DAHL ENGINEERING

SLED - TEST


Project: Medema MC1144 w. Dahl Docking


Editor: CDP	Specification: ISO10542 SWM / ISO7176-19
Date: 05/23/2022	Test type: Homolgation Test
File: Medema2022-015	Test structure: Sled
Sensors: MWS 4301, S/N-Nr.:SA-0263	Test sample: Medema MC 1144 Spinalus 3
Measurement: A/D Karte, DT 321	Comment to sample: With Dahl Docking
Analysis Sequence: Standard	Occupant: HybridII 50% Male
Sled velocity: 48.9 km/h	General comment:


SLED ACCELERATION



Pre- test photos











Post test photos









Post test photos





